

TECHNICAL SERVICE BULLETIN

SUBJECT: Axial Hub Introduction

Products Affected: Axial Product Line

Effective Date: 14-Feb-2008

Telma is committed to a philosophy of continuous improvement as a way of enhancing the end-user's experience with our product. We are continually examining service data to see if we can identify any trends, which highlight information that could be useful to our customers.

This service bulletin relates to a recommended improvement that customers can make to ensure, as close to factory type quality as possible, for models that have suffered a bearing failure. Telma is introducing a complete hub assembly that includes all of the bearings, seals, shims, etc that would be necessary when replacing or repairing a retarder that has suffered a bearing failure. The assembly is pre-greased and ready to install.

To reduce the amount of downtime with the product it is recommended that the dealer follow the hub replacement procedure for AC and AD retarders.

Hub replacement part numbers by Telma model.

AC50-55	VB 107 963
AC50-80	VB 107 956
AC51-00	
AC61-25	VB 107 969
AC61-35	VB 107 962
AC61-60	
AC72-00	VB 107 961
AC81-80	VB 107 957
AC82-45	
AC83-00	
AC83-31	
AD50-55	VB 107 980
AD50-90	
AD61-30	VB 107 979
AD61-55	
AD72-00	VB 107 978
AD72-45	
AD72-60	
AE30-32	VB 107 555
AE30-35	