



TELMA RETARDER, INC.
 870 Lively Blvd., Wood Dale, IL 60191
 Tel: (847) 593-1098 • Fax: (847) 593-3592

www.TelmaUSA.com

TL103034

Revised: 28-JAN-11

TECHNICAL SERVICE BULLETIN

SUBJECT: Installation of a Telma on an Autocar using inside chassis brackets
Products Affected: BH301157
Effective Date: 3-SEP-09
 For new installations with an AD72-45 retarder.
 Inside Mount Autocar Chassis.

RELEASED FOR AUTOCAR
 WX-WXLL-ACX CHASSIS
 INSIDE FRAME DIMENSION OF 33.125"
 FRAME WITH LINER

| WX/WXLL/ACX TELMA INSTALLATION | |
|--------------------------------|----------|
| ITEM DESCRIPTION | QUANTITY |
| 1. CHASSIS BRACKET | 2 |
| 2. SIDE PLATE BRACKET | 2 |
| 3. TREP WASHER | 8 |
| 4. SIDE PLATE BOLT | 8 |
| 5. SHOCKMOUNT BOLT | 4 |
| 6. WASHER | 8 |
| 7. SHOCKMOUNT WASHER | 8 |
| 8. SHOCKMOUNT | 4 |
| 9. NUT | 4 |

USE MEDIUM STRENGTH LOCTITE ON ALL FASTENERS AND MARK WITH PAINT AFTER TIGHTENING TO PROPER TORQUE

Isometric view Front Side

RELEASED FOR AUTOCAR
 WX-WXLL-ACX CHASSIS
 INSIDE FRAME DIMENSION OF 33.625"
 FRAME WITHOUT LINER

| WX/WXLL/ACX TELMA INSTALLATION | |
|--------------------------------|----------|
| ITEM DESCRIPTION | QUANTITY |
| 1. CHASSIS BRACKET | 2 |
| 2. SIDE PLATE BRACKET | 2 |
| 3. TREP WASHER | 8 |
| 4. SIDE PLATE BOLT | 8 |
| 5. SHOCKMOUNT BOLT | 4 |
| 6. WASHER | 8 |
| 7. SHOCKMOUNT WASHER | 8 |
| 8. SHOCKMOUNT | 4 |
| 9. NUT | 4 |

USE MEDIUM STRENGTH LOCTITE ON ALL FASTENERS AND MARK WITH PAINT AFTER TIGHTENING TO PROPER TORQUE

Isometric view Front Side

This document is the exclusive property of TELMA RETARDER INC. It cannot be copied, modified, forwarded, or given to any third party without prior agreement from TELMA RETARDER INC. Any infringement will immediately involve legal action.