



TELMA RETARDER, INC.

Tel: (847) 593-1098 • Fax: (847) 593-3592

[www.TelmaUSA.com](http://www.TelmaUSA.com)

**TL105046**

Revised: 24feb21jh

## Technical Service Bulletin

**SUBJECT:** Driveline length modification when installing focal retarders on Meritor RS series axles.

**Products Affected:** All Focal retarders

**Effective Date:** 15nov 1992

Telma is committed to a philosophy of continuous improvement as a way of enhancing the end-user's experience with our product.

### Meritor RS160 Series

U-Joint series	Original Meritor Yoke #	Shorten drive by
1710	17NYS38-28	3.50"
1710	17NYS38-24	3.29"
1710	17NYS38-29	3.29"
1810	18NYS38-13	3.55"

### Meritor RS180 Series

U-Joint series	Original Meritor Yoke #	Shorten drive by
1710	17NYS38-217A	2.06"
1710	17NYS38-18A	1.40"
1810	18N 4-3201	3.07"

Contact Telma Technical Support if the original Meritor Yoke is not listed above.

If you have any questions, contact Telma customer support at 800 797-7714, go to the Telma Web site at [www.telmausa.com](http://www.telmausa.com), or send an email to [engineering@telmacse.com](mailto:engineering@telmacse.com) with your questions 24 hours a day / 7 days a week.

This document is the exclusive property of TELMA RETARDER INC. It cannot be copied, modified, forwarded, or given to any third party without prior agreement from TELMA RETARDER INC. Any infringement will immediately involve legal action.