

TECHNICAL SERVICE BULLETIN

SUBJECT: Warranty

Products Affected: Focal

Effective Date: 10-OCT-05

The Telma warranty does not cover a Telma component which fails, malfunctions or is damaged as a result of accident, abuse or improper or insufficient maintenance or repair.

In particular, failure of vehicle suspension components allowing excessive and unusual movement of the axle resulting in damage to the Telma stator, connecting block or other Telma component due to contact with the frame rail is not covered under the Telma warranty.

If such damage occurs, the damaged Telma components must be repaired or replaced immediately to avoid possible additional and consequential damage.

This document is the exclusive property of TELMA RETARDER INC. It cannot be copied, modified, forwarded, or given to any third party without prior agreement from TELMA RETARDER INC. Any infringement will immediately involve legal action.