


TECHNICAL SERVICE BULLETIN

SUBJECT: Lip Seal Change
Products Affected: All AC8 Axial Telma Retarders
Effective Serial #: 394334 and after

For serial numbers after 394334 the bearing Lip Seal has changed to part number VF400360. For serial numbers before 394334 the bearing lip seal is still part number VF400340.

If you have any questions, contact Telma customer support at 800 797-7714 or go to the Telma helpdesk at www.telmausa.com and submit a ticket with your questions 24 hours a day / 7 days a week.



#37 Lip Seal
Effects Only:
 AC8 Model retarders (ex. AC82-45, AC82-70)
 Before Serial 394334: VF400340
 After Serial 394334: VF400360

This document is the exclusive property of TELMA RETARDER INC. It cannot be copied, modified, forwarded, or given to any third party without prior agreement from TELMA RETARDER INC. Any infringement will immediately involve legal action.