



TELMA RETARDER, INC.
 870 Lively Blvd., Wood Dale, IL 60191
 Tel: (847) 593-1098 • Fax: (847) 593-3592

www.TelmaUSA.com

TL103031

Date: 28-JAN-11

TECHNICAL SERVICE BULLETIN

SUBJECT: Installation of a Telma on a Mack MR / LE using inside chassis brackets
Products Affected: BH201157 / BH301157
Effective Date: 1-May-2007
 For new installations with an AD72-45 retarder.
 Inside Mount Mack MR-LE Chassis.

RELEASED FOR MACK TRUCKS
 MRU - LEU CHASSIS
 INSIDE FRAME DIMENSION OF 32.75"
 FRAME WITHOUT LINER

MR / LE TELMA INSTALLATION		
ITEM	DESCRIPTION	QUANTITY
1.	CHASSIS BRACKET	2
2.	SIDE PLATE BRACKET	2
3.	TREPP WASHER	8
4.	SIDE PLATE BOLT	8
5.	SHOCKMOUNT BOLT	4
6.	WASHER	8
7.	SHOCKMOUNT WASHER	8
8.	SHOCKMOUNT	4
9.	NUT	4

RELEASED FOR MACK TRUCKS
 MRU - LEU CHASSIS
 INSIDE FRAME DIMENSION OF 32.25"
 FRAME WITH LINER

MR / LE TELMA INSTALLATION		
ITEM	DESCRIPTION	QUANTITY
1.	CHASSIS BRACKET	2
2.	SIDE PLATE BRACKET	2
3.	TREPP WASHER	8
4.	SIDE PLATE BOLT	8
5.	SHOCKMOUNT BOLT	4
6.	WASHER	8
7.	SHOCKMOUNT WASHER	8
8.	SHOCKMOUNT	4
9.	NUT	4

This document is the exclusive property of TELMA RETARDER INC. It cannot be copied, modified, forwarded, or given to any third party without prior agreement from TELMA RETARDER INC. Any infringement will immediately involve legal action.