

TECHNICAL SERVICE BULLETIN

SUBJECT: New grease seal kits

Products Affected: All Axial

Effective Date: 12jan08

New grease seal kits are now available which include a replacement set of grease seals (parts catalog item 37), the seal races (parts catalog item 38) and the snap rings (parts catalog item 35).

These parts, (seal, snap ring, seal race) are no longer available separately.

Below are the new part numbers for these kits.

If you have any questions, contact Telma customer support at 800 797-7714 or go to the Telma website at www.telmausa.com for more information 24 hours a day / 7 days a week.

Retarder Model	Description
Up to serial number 394333 (28mar05): AC81-80, AC82-45, AC82-70, AC83-30, AC83-31	VB 107 905
Up to serial number 394333 (28mar05): AC72-00 AD72-00, AD72-60	VB 107 942
From serial number 394334 (29mar05): AC81-80, AC82-45, AC82-70, AC83-30, AC83-31, AC72-00 AD72-00, AD72-45, AD72-60	VB 107 906
AC61-25, AC61-35, AC61-60 AD6130, AD61-55	VB 107 907
AC50-65, AC50-80, AC51-00	VB 107 908
AC50-55 AD50-55, AD50-60, AD50-90	VB 107 909
AE30-32, AE30-35	VB 107 917

This document is the exclusive property of TELMA RETARDER INC. It cannot be copied, modified, forwarded, or given to any third party without prior agreement from TELMA RETARDER INC. Any infringement will immediately involve legal action.