



**TELMA RETARDER, INC.**  
 Tel: (847) 593-1098 • Fax: (847) 593-3592

**TL105076**

Revised: 07jul21jh

**TECHNICAL SERVICE BULLETIN**

**SUBJECT:** New grease seal kits  
**Products Affected:** All Axial  
**Effective Date:** 12jan08

Grease seal kits are available for the Axial models in the table below.



Retarder Model	Description
Up to serial number 394333 (28mar05): AC81-80, AC82-45, AC82-70, AC83-30, AC83-31	N/A
Up to serial number 394333 (28mar05): AC72-00 AD72-00, AD72-60	N/A
From serial number 394334 (29mar05): AC81-80, AC82-45, AC82-70, AC83-30, AC83-31, AC72-00 AD72-00, AD72-45, AD72-60, AF81-80, AF83-20, AF83-40, AF83-60	VA1002311
AC61-25, AC61-35, AC61-60 AD6130, AD61-55	VA1002310
AC50-65, AC50-80, AC51-00	N/A
AC50-55 AD50-55, AD50-60, AD50-90	VA1001374
AF50-55, AF50-90	VA1001375
AF30-35	N/A
AE30-32, AE30-35	N/A

This document is the exclusive property of TELMA RETARDER INC. It cannot be copied, modified, forwarded, or given to any third party without prior agreement from TELMA RETARDER INC. Any infringement will immediately involve legal action.