



TELMA RETARDER, INC.

Tel: (847) 593-1098 • Fax: (847) 593-3592

[www.TelmaUSA.com](http://www.TelmaUSA.com)

**TL105043**

Revised: 10nov2015

## Technical Service Bulletin

**SUBJECT:** Installation Drawing Policy  
**Products Affected:** All  
**Effective Date:** July 21, 1992

In order to minimize installation problems it has always been Telma's policy and practice to provide authorized Telma installation centers with specific installation instructions based on measurements sent to us. To do this the authorized installer submits a [Drawing Request](#) on our website and our engineering department designs the driveline layout and sends back detailed installation instructions to the installer.

It is the responsibility of the installer to ensure that the Telma is installed properly.

The Telma warranty may be voided if it is determined that the torsional and inertial driveline accelerations are beyond the acceptable Telma and industry standard limits for applications with driveline mounted electromagnetic retarders.

If you have any questions, contact Telma customer support at 800 797-7714, go to the Telma Web site at [www.telmausa.com](http://www.telmausa.com), or send an email to [engineering@telmacse.com](mailto:engineering@telmacse.com) with your questions 24 hours a day / 7 days a week.

This document is the exclusive property of TELMA RETARDER INC. It cannot be copied, modified, forwarded, or given to any third party without prior agreement from TELMA RETARDER INC. Any infringement will immediately involve legal action.