





TL134065 WIRING DIAGRAM TRCM with rotary foot switch and no CAN

16aug16jh



RELAY BOX
JD331121 (12V)

LIGHT BAR
DISPLAY
TIG11010 (12V)



ABS control connection (N.D., ground during ABS event)	Pin
WABCO C HYD	11
WABCO D CAB HYD 15PIN	12
WABCO D FRAME HYD X2	7
WABCO E HYD	2

CONNECT TO PC FOR FINAL CONFIGURATION CHECK AND DIAGNOSTICS

1. check proper transducer set point voltages
2. set speed to 0 mph to test function with vehicle stopped
3. set speed back to 1 mph or less before release
4. road test to observe Telma cutoff speed.

If needed: change speed setting to desired Telma cutoff speed up to 2 mph.